

## HYOSUNG Service Bulletin

---#77, SUNGSAN-DONG, CHANGWON-CITY,KYUNGNAM,KOREA Tel.82-55-276-7385,Fax.82-55-274-0585---

SUBJECT	Cautions when reparing Speedometer Sensor
MODEL	GV700C
EFFECTIVE F/M NO	Refer to below information
PURPOSE	Calling operators attention when reparing speedometer sensor of GV700C to prevent occurrence of defectiveness.
DETAIL	<ul> <li>Symptoms</li> <li>Speed indicator got out of control.</li> <li>Engine jerks when its acceleration.         <ul> <li>(In case of DELPHI system, speedometer works as sensor which is affected its fuel injection)</li> </ul> </li> <li>Cause of defectiveness         <ul> <li>The wire of speedometer sensor interfered by front brake disk or wheel.</li> </ul> </li> </ul>
NOTE	<ul> <li>Solution</li> <li>1) When speed indicator works poorly, it should be checked its wire damage or sagging.</li> <li>2) In case of GV700C, there is high possibility of interference between front wheel, disk assembly and sensor. So it should be clamped tightly to prevent damage or sagging.</li> </ul>
Effective Vin. No. & Part No.	N/A